


Trc1 — S11 SWR 1 U/ Ref 1 U

1 ▾



Link to [Common Settings](#)

Link to Channel: [Ch1](#)

Link to Trace: [Trc1](#)

Link to [Instrument Information All Sets Calibration Pool Connectivity](#)

---

## Set Information

### Common Settings

Reference Frequency: Internal

### Channel Ch1

Continuous Linear Frequency Sweep, 201 points

Channel Base Frequency (fb): 100 MHz ... 6 GHz

Channel Base Power (Pb): -10 dBm

Sweep Time: 21.8 ms (Auto)

Auto AGC Configuration

Free Running Trigger

Measurement Bandwidth: 10 kHz, Normal Selectivity

System Error Correction Inactive

User Correction Data

No System Error Correction Data Available

No Power Correction Data Available

Channel used by Trace: [Trc1](#)

Port Configuration

Port 1

Reference Impedance: 50  $\Omega$

Connector: N 50  $\Omega$  female

Port 2

Reference Impedance: 50  $\Omega$

Connector: N 50  $\Omega$  female

### Trace Trc1

Measured in Channel [Ch1](#) , Displayed in Diagram Area 1

Measured Quantity:  $S_{11}$

No System Error Correction Active

No Power Correction Active

Format: SWR



CPU\_ID 1206.3300.00-134712/000 Rev 0  
Bios R&S ZND W10 1.02  
ConfigurationScript 1.42

---

### Memory State

Usage 31 %  
Physical Memory total 3777 MB  
Physical Memory available 2579 MB  
Page File total 7873 MB  
Page File available 6545 MB

---

### Calibration Pool

Calibrations in Pool: 0

---

### Connectivity

#### MAC Addresses

00-E0-33-08-FF-1D Ethernet

#### IP Addresses

IP Address: 192.168.100.57 Subnet Mask: 255.255.255.0

IP Address: 127.0.0.1 (Localhost) Subnet Mask: 255.0.0.0

#### GPIB

GPIB Driver installed  
GPIB Adapter not operational  
GPIB Bus Address 20  
GPIB Byte Order Little Endian (Default)  
Parser Language DEFAULT

**VISA**

VISA Manufacturer	Rohde & Schwarz GmbH
VISA Version	5.8.5

**USB**

VXI-PnP for NRP	Rev 3.6.0.0, 10/2018
rsnrpz_x64.sys	
NrpControl2_64.dll	3.72.3.0
rsnrpz_64.dll	3.6.0.0
rscomzv.dll	0.83
usbbulkx64.sys	
usbbulk.dll	1.2.4.0
znz8x_dll.dll	2.6.0
znz154.dll	

**LXI**

LXI Engine	installed
LXI Service	disabled

**DirectCtrl**

DirectCtrl Board	not installed
------------------	---------------

---